

W.Meyer Motoreninstandsetzungen GmbH & Co.KG
Konauer Straße 21
21354 Bleckede

Telefon: 05852-950-0
Telefax: 05852-650-66
Email: info@meyermotoren.de
Homepage: www.meyermotoren.de



Details zum Artikel

01.099.898.0 MM Teil-Motor VW 1.8 16V FSI

Lieferumfang

Motorblock mit Kurbelwelle, Pleuel und Kolben

Preis

Preise werden nur in unserem Webkatalog eingeloggten Nutzern angezeigt

Passend für

AUDI A3 (8P1) 1.8 TFSI
AUDI A3 (8P1) 1.8 TFSI quattro
AUDI A3 Cabriolet (8P7) 1.8 TFSI
AUDI A3 Sportback (8PA) 1.8 TFSI
AUDI A3 Sportback (8PA) 1.8 TFSI quattro
AUDI A4 B8 (8K2) 1.8 TFSI
AUDI A4 B8 (8K2) 1.8 TFSI
AUDI A4 B8 (8K2) 1.8 TFSI quattro
AUDI A4 B8 Avant (8K5) 1.8 TFSI
AUDI A4 B8 Avant (8K5) 1.8 TFSI
AUDI A4 B8 Avant (8K5) 1.8 TFSI quattro
AUDI A5 (8T3) 1.8 TFSI
AUDI A5 Cabriolet (8F7) 1.8 TFSI
AUDI A5 Sportback (8TA) 1.8 TFSI
AUDI TT (8J3) 1.8 TFSI
AUDI TT Roadster (8J9) 1.8 TFSI
SEAT ALHAMBRA (710, 711) 1.8 TSI

SEAT ALTEA (5P1) 1.8 TFSI
SEAT ALTEA XL (5P5, 5P8) 1.8 TFSI
SEAT EXEO (3R2) 1.8 TSI
SEAT EXEO (3R2) 1.8 TSI
SEAT EXEO ST (3R5) 1.8 TSI
SEAT EXEO ST (3R5) 1.8 TSI
SEAT LEON (1P1) 1.8 TSI
SEAT TOLEDO III (5P2) 1.8 TFSI
SKODA OCTAVIA II (1Z3) 1.8 TSI
SKODA OCTAVIA II Combi (1Z5) 1.8 TSI
SKODA OCTAVIA II Combi (1Z5) 1.8 TSI 4x4
SKODA SUPERB II (3T4) 1.8 TSI
SKODA SUPERB II (3T4) 1.8 TSI 4x4
SKODA SUPERB II Kombi (3T5) 1.8 TSI
SKODA SUPERB II Kombi (3T5) 1.8 TSI 4x4
SKODA YETI (5L) 1.8 TSI 4x4
VW CC B7 (358) 1.8 TSI
VW GOLF VI (5K1) 1.8 TSI
VW PASSAT ALLTRACK B7 (365) 1.8 TSI
VW PASSAT B6 (3C2) 1.8 TSI
VW PASSAT B6 Variant (3C5) 1.8 TSI
VW PASSAT B7 (362) 1.8 TSI
VW PASSAT B7 Variant (365) 1.8 TSI
VW PASSAT CC B6 (357) 1.8 TSI

Bilder




Bild 1 von 4




Bild 2 von 4



Bild 3 von 4



Bild 4 von 4