

W.Meyer Motoreninstandsetzungen GmbH & Co.KG
Konauer Straße 21
21354 Bleckede

Telefon: 05852-950-0
Telefax: 05852-650-66
Email: info@meyermotoren.de
Homepage: www.meyermotoren.de



Details zum Artikel

01.403.725.0 MM Zylinderkopf NEU o.NW VW 1.8

Lieferumfang

NEUTEIL mit Ventilen, ohne Nockenwelle

Passend für

AUDI A3 (8L1) 1.8
AUDI A3 (8L1) 1.8 T
AUDI A3 (8L1) 1.8 T
AUDI A3 (8L1) 1.8 T quattro
AUDI A3 (8L1) 1.8 T quattro
AUDI A4 B5 (8D2) 1.8
AUDI A4 B5 (8D2) 1.8 T
AUDI A4 B5 (8D2) 1.8 T
AUDI A4 B5 (8D2) 1.8 T quattro
AUDI A4 B5 (8D2) 1.8 T quattro
AUDI A4 B5 (8D2) 1.8 quattro
AUDI A4 B5 Avant (8D5) 1.8
AUDI A4 B5 Avant (8D5) 1.8 T
AUDI A4 B5 Avant (8D5) 1.8 T
AUDI A4 B5 Avant (8D5) 1.8 T quattro
AUDI A4 B5 Avant (8D5) 1.8 T quattro
AUDI A4 B5 Avant (8D5) 1.8 quattro
AUDI A6 C4 (4A2) 1.8
AUDI A6 C4 (4A2) 1.8 quattro
AUDI A6 C4 Avant (4A5) 1.8
AUDI A6 C4 Avant (4A5) 1.8 quattro

AUDI A6 C5 (4B2) 1.8 T
AUDI A6 C5 (4B2) 1.8 T
AUDI A6 C5 (4B2) 1.8 T quattro
AUDI A6 C5 (4B2) 1.8 T quattro
AUDI A6 C5 Avant (4B5) 1.8 T
AUDI A6 C5 Avant (4B5) 1.8 T
AUDI A6 C5 Avant (4B5) 1.8 T quattro
AUDI A6 C5 Avant (4B5) 1.8 T quattro
AUDI CABRIOLET B3 (8G7) 1.8
AUDI TT (8N3) 1.8 T
AUDI TT (8N3) 1.8 T quattro
AUDI TT Roadster (8N9) 1.8 T
AUDI TT Roadster (8N9) 1.8 T quattro
SEAT LEON (1M1) 1.8 20V
SEAT LEON (1M1) 1.8 20V T 4
SEAT TOLEDO II (1M2) 1.8 20V
SKODA OCTAVIA I (1U2) 1.8
SKODA OCTAVIA I Combi (1U5) 1.8 20V
VW BORA I (1J2) 1.8
VW BORA I (1J2) 1.8 4motion
VW BORA Variant (1J6) 1.8 4motion
VW GOLF IV (1J1) 1.8
VW GOLF IV (1J1) 1.8 4motion
VW GOLF IV (1J1) 1.8 T
VW GOLF IV Variant (1J5) 1.8 4motion
VW PASSAT B5 (3B2) 1.8
VW PASSAT B5 (3B2) 1.8 Syncro/4motion
VW PASSAT B5 (3B2) 1.8 T
VW PASSAT B5 Variant (3B5) 1.8
VW PASSAT B5 Variant (3B5) 1.8 Syncro/4motion
VW PASSAT B5 Variant (3B5) 1.8 T

Bilder